



STATE OF RHODE ISLAND AND PROVIDENCE PLANTATIONS

DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

75 Davis Street  
Providence, R.I. 02908

26 January 1988

Bristol - 1  
Coventry - 3  
Cranston - 1  
Cumberland - 2  
Johnston - 5  
Lincoln - 1  
North Scituate - 2  
Richmond - 1  
South Kingstown - 3

Mr. Don Smith  
EPA - Region I  
JFK Federal Building  
Boston, MA 02203



SEMS DocID 589362

Superfund Records Center  
SITE: Boulter  
BREAK: 1.1  
OTHER: \_\_\_\_\_

Dear Mr. <sup>Don</sup>Smith:

As a follow-up to our telephone conversation on Wednesday, January 13, 1988, I have listed a few RI CERCLIS sites that I recommend be considered for further investigation under the Pre-Remedial Program. Many of these sites were selected because, either they were given a high priority at the Preliminary Assessment Stage and there has been, and is currently, no further investigation or remediation being conducted or, they have had a Site Inspection (SI) or Ranking (HRS) conducted under the former SI/HRS program and should be investigated under the revised SI/HRS program. The sites I am proposing are as follows:

<u>Site Name</u>	<u>Location</u>	<u>Pre-Remedial Activity</u>
H & H Rack, Inc.	North Scituate	SSI/LSI
R & R Jewelry, Inc.	North Scituate	could be done concurrently
S. Kingstown L.F. #2	South Kingstown	LSI/HRS
Septage Disposal Area	South Kingstown	SSI/LSI
Photek Inc. Property	South Kingstown	LSI/HRS
Coventry Municipal L.F.	Coventry	LSI/HRS
Great Lakes Container	Coventry	LSI/HRS
Washington Well #1 and associated sites	Coventry	SSI/LSI
Cumberland Municipal Landfill	Cumberland	SSI/LSI
Boulter Farm Area	Cumberland	LSI/HRS
Silvestri Property	Warwick	SSI/LSI
Truck Away of RI, Inc.	Warwick	LSI/HRS

Tuckers Industrial		
Dump	Johnston	SSI/LSI ✓
M.E. Adams Co.	Johnston	SSI/LSI ✓
L. Vinagro & J. Vinagro		
Landfills (2 sites)	Johnston	SSI/LSI ✓
Bible Speaks & Associated		
Sites	Johnston	LSI/HRS ✓
Bristol Landfill	Bristol	LSI/HRS ✓
Cranston Sanitary L.F.	Cranston	LSI/HRS ✓
Kenyon Piece Landfill	Richmond	LSI/HRS
Manville Well Field	Lincoln	SSI/LSI ✓

I would like to discuss the availability of your Field Investigative Team (FIT) to assist the State with investigations at as many of these sites as possible. If it is convenient with you, I suggest we meet during the week of 15 February 1988.

Also during our recent conversation, we discussed the South Kingstown Landfill #2 and the URI Disposal Area. You agreed to use your FIT Contractor to assist the State with further investigations (LSI) at these sites and you anticipated developing a scope of work by April 1988. I will have staff from this office available to assist you with this work and I would like to be involved with the development of the scope of work. Based upon the sampling data we have received to date, I would recommend the installation of additional monitoring wells at these sites. Since there are no additional monitoring wells to be installed at the Rose Hill Landfill (approximately 2.5 miles from the Plains Road sites), I would like to request that this task be included in the LSI scope of work for the S. Kingstown Landfill #2/URI Disposal Area. In addition, I have enclosed a letter prepared by a University of Rhode Island professor for the Town of South Kingstown outlining his recommendations to further characterize the sites.

I appreciate your cooperation and will be contacting you to schedule a meeting to discuss these issues.

If you have any questions concerning this letter, please contact me at 277-2797.

Very truly yours,



Alicia Good, Principal Engineer  
Division of Air & Hazardous Materials

cc: Thomas D. Getz  
Ruth Leabman

donsm-ag/L1